



Top Plate
9 M3-0.5 Threaded



Bottom Mounting Plate
4 M3 Clearance Holes Counter
Sunk for Cap Screws



To attach Bottom Plate:
 Move Plate to Extream in One Direction:
 This will expose 2 countersunk holes.
 Attach using 2 Cap Screws in countersunk holes
 Move Plate to Opposite Extream Direction:
 This will expose the other 2 countersunk holes.
 Attach using 2 Cap Screws in countersunk holes



Cap Screw (Not Supplied)
For reference only

Information obtained from or supplied by Mpja.com or Marlin P. Jones and Associates inc. is supplied as a service to our customers and accuracy is not guaranteed nor is it definitive of any particular part or manufacturer. Use of information and suitability for any application is at users own discretion and user assumes all risk.

www.mpja.com

Title ADJUSTABLE 3 AXIS STAGE		
Size	Document Number 33383 MI	Rev.
Date	Sheet	